

REFERENCES

1. 3G/4G/5G coverage map Ukraine. (2025). Retrieved from <https://surl.li/xhpn0i>
2. Abdalla, H. A. (2002). Assessment of damages and repair of antenna tower concrete foundations. *Construction and Building Materials*, 16(8), 527–534. [https://doi.org/10.1016/S0950-0618\(02\)00028-4](https://doi.org/10.1016/S0950-0618(02)00028-4)
3. Agudelo-Vera, C. M., Leduc, W. R., Mels, A. R., & Rijnaarts, H. H. (2012). Harvesting urban resources towards more resilient cities. *Resources, Conservation and Recycling*, 64, 3–12. <https://doi.org/10.1016/j.resconrec.2012.01.014>
4. Al-Bazoon, M., & Arora, J. (2024). Design of structures subjected to blast loads: Analysis and design review. *Misan Journal of Engineering Sciences*, 3(1), 16–37. <https://doi.org/10.61263/mjes.v3i1.70>
5. An explosion occurred in a building at the Institute of Communications: Rescuers evacuated people. (2023). Poltavashchyna (Internet edition). Retrieved from <https://poltava.to/news/72509/>
6. Baghchesaraei, O. R., Lavasani, H. H., & Baghchesaraei, A. (2016). Behavior of prefabricated structures in developed and developing countries. *Bulletin de la Société Royale des Sciences de Liège*, 85, 1229–1234. <https://doi.org/10.25518/0037-9565.5997>
7. Bannikov, D. O. (2019). Accidents and failures of steel thin-walled cylindrical silos for grain crops. *Bridges and Tunnels: Theory, Research, Practice*, (15), 6–17. <https://doi.org/10.15802/bttrp2019/172336>
8. Bibik, M. V., Bibik, V. M., & Bibik, I. O. (2014). Classification of silo grain storages. *Sectoral Mechanical Engineering and Construction*, 1(40), 157–165. Retrieved from <https://journals.nupp.edu.ua/znp/article/view/235>
9. Bibik, M. V., Bibik, V. M., Ulchenko, R. M., & Bibik, I. O. (2017). Classification of accidents and damages of steel silos. *Sectoral Mechanical Engineering and Construction*, 1(40), 175–183. Retrieved from <https://journals.nupp.edu.ua/znp/article/view/236>
10. Binkevych, K. O., Volodymyrov, A. V., & Kolchanov, A. V. (2024). Analysis of destructions and strengthening methods of precast reinforced-concrete floor panels. *Coll. Sc. Papers UkrDUZT*, 208, 67–79. <https://doi.org/10.33644/2313-6679-3-2023-7>
11. Bohachenko, S. V., Shatov, S. V., & Rudin, A. A. (2023). Diagnostics of the technical condition of building structures subjected to non-design explosive impacts. *Ukrainian Journal of Construction and Architecture*, (2[014]), 100–107. <https://doi.org/10.30838/J.BPSACEA.2312.250423.100.937>
12. Boichenko, M. V. (2023). Recovery and development of transport infrastructure in the post-war period. *Economic Bulletin of Donbas*, 3(73), 132–137. [https://doi.org/10.12958/1817-3772-2023-3\(73\)-132-137](https://doi.org/10.12958/1817-3772-2023-3(73)-132-137)
13. Brzev, S., & Guevara-Perez, T. (2010). Precast concrete construction. British Columbia Institute of Technology.

REFERENCES

14. CEN. (2012). *EN 1996-1-1: Eurocode 6 – Design of masonry structures. Part 1-1: General rules for reinforced and unreinforced masonry structures* (2005 + A1:2012). Brussels: CEN.
15. Chamasemani, N. F., Kelishadi, M., Mostafaei, H., Najvani, M. A. D., & Mashayekhi, M. (2024). Environmental impacts of reinforced concrete buildings: Comparing common and sustainable materials – A case study. *Construction Materials*, 4, 1–15. <https://doi.org/10.3390/constrmater4010001>
16. Critical infrastructure: Photos of destruction. (2024). Retrieved from <https://destruction.in.ua/ua/categories/critical-buildings>
17. Dakov, D., Georgiev, V., & Boiadjieva, R. (2022). Failures of steel silos for grain storage – Fortuity or underestimated risk. In *IABSE Congress: Bridges and Structures: Connection, Integration and Harmonisation* (pp. 1617–1623). Nanjing, China: IABSE.
18. Demyanenko, O. O., & Militskyi, K. O. (2024). Features of technical inspection of multi-storey residential buildings damaged by missile strikes. *Construction Production*, 76, 57–62. <https://doi.org/10.36750/2524-2555.76.57-62>
19. Department of Philosophy & Department of Mechanical Engineering, Texas A&M University. (1992). TV antenna tower collapse. *Engineering Ethics (NSF Grant DIR-9012252)*. <https://doi.org/10.18130/34s5-ts50>
20. *Destruction in Ukraine*. Retrieved from <https://destruction.in.ua/ua>
21. *Destruction in Ukraine (photo database of ruined houses)*. Retrieved from <https://destruction.in.ua/ua/categories/houses>
22. *Destruction in Ukraine (transport system photos)*. Retrieved from <https://destruction.in.ua/ua/categories/transport-system> (accessed 10 Sept 2025).
23. DSTU 9181:2022. (2023). *Transport structures. Highway bridges. Guideline for assessment and forecasting of technical condition of road bridges*. Kyiv: State Enterprise “UkrNDNC”.
24. DSTU 9273:2024. (2024). *Guidelines for the inspection of buildings and structures to determine and assess their technical condition: Mechanical resistance and stability*. Kyiv: DP “UkrNDNTS”.
25. DSTU-N B EN 1993-4-1:2012. (2020). *Eurocode 3: Design of steel structures. Part 4-1: Silos (with Amendments No. 1 and No. 2) (EN 1993-4-1:2007 IDT + NA:2013 + A1:2017 IDT)*. Kyiv: State Enterprise “UkrNDNC”.
26. DBN V.2.3-22:2009. (2009). *Transport structures. Bridges and pipes. Basic design requirements*. Kyiv: NTU.
27. DBN V.2.6-98:2009. (2011). *Concrete and reinforced concrete structures. Basic provisions*. Retrieved from <https://dbn.co.ua/load/normativy/dbn/1-1-0-792>
28. Dutta, A. B. (2013). Study of types of failures in silos. *International Global Research Analysis*, 2(6), 41–43.
29. Explosion in a house in Poltava: Rescue work completed, preliminary version of the tragedy named (photo). (2023). TSN (online edition). Retrieved from <https://tsn.ua/ukrayina/vibuh-u-budinku-poltavi-ryatuvalni-roboti-zavershenonazvano-poperednyu-versiyu-tragediyi-foto-2385538.html>
30. Folić, R., Laban, M., & Milanko, V. (2011). Reliability and sustainability analysis of large panel residential buildings in Sofia, Skopje and Novi Sad.

Facta Universitatis, Series: Architecture and Civil Engineering, 9, 161–176. <https://doi.org/10.2298/FUACE1101161F>

31. Francioli, M., Petrini, F., Olmati, P., & Bontempi, F. (2021). Robustness of reinforced concrete frames against blast-induced progressive collapse. *Vibration*, 4(3), 722–742. <https://doi.org/10.3390/vibration4030040>

32. Górski, W. (2021). Problems of early large-panel structures in Poland. *Acta Scientiarum Polonorum. Architectura*, 20, 45–53. <https://doi.org/10.22630/ASPA.2021.20.3.25>

33. Gul, A., Alam, B., Iqbal, M. J., Ahmed, W., Shahzada, K., Javed, M. H., & Khan, E. A. (2021). Impact of length and percent dosage of recycled steel fibers on the mechanical properties of concrete. *Civil Engineering Journal*, 7(9), 1508–1522. <https://doi.org/10.28991/cej-2021-03091750>

34. Hasenko, A. V., & Padun, Yu. O. (2025). Analysis of damage to communication antenna structures resulting from military operations. *Tavria Scientific Bulletin. Series: Technical Sciences*, 5.

35. Hasenko, A. V., & Padun, Yu. O. (2025, October 20–21). Generalization of damage to communication antenna structures caused by military actions. In *Proceedings of the XX International Scientific-Practical Conference “Innovative Technologies in Construction, Civil Engineering and Architecture”*. Dnipro: State Higher Educational Institution of the Academy of Sciences of Ukraine.

36. Hasenko, A., Padun, Y., & Bibik, M. (2023). The mobile communication antenna structures classification. *Academic Journal. Industrial Machine Building. Civil Engineering*, 2(61), 29–35. <https://doi.org/10.26906/znp.2023.61.3850>

37. Hasenko, L. V., & Baranets, P. D. (2024). Typical damages of bridge structures in areas of military operations in Ukraine. In *Proceedings of the 76th Scientific Conference of Professors, Lecturers, Researchers, Postgraduates and Students* (pp. 49–50). Poltava: National University “Yurii Kondratiuk Poltava Polytechnic”. Retrieved from <https://reposit.nupp.edu.ua/handle/PoltNTU/15643>

38. Hassiev, S., et al. (2023). Modern ways of development of science and the latest theories: Abstracts of the XIII International Scientific and Practical Conference, December 11–13, 2023, Madrid, Spain. Eu-Conf. Retrieved from <https://eu-conf.com/wp-content/uploads/2023/11/MODERN-WAYS-OF-DEVELOPMENT-OF-SCIENCE-AND-THE-LATEST-THEORIES.pdf>

39. How to transform a “Khrushchevka” into a modern energy-efficient building. (2024). Retrieved from <https://1news.zp.ua/yak-peretvoriti-hrushhovkuna-suchasnij-energoefektivnij-budinok-dosvid-vidnovlennya-poshkodzhennih-rosijskimi-raketami-budinkiv-u-zaporizhzhii/>

40. Hryhorovskiy, A. P. (2022). Comparative analysis and selection of organizational-technological solutions for eliminating the consequences of accidental destructions. *Construction Production*, 74, 17–24.

41. Hrynevych, E., Haievyi, Yu., Vyatkin, V., & Karzhynero, T. I. (2021). Problems of reconstruction of residential buildings constructed in the 1960–1970s in Kharkiv. *Scientific Bulletin of Construction*, 104(2), 140–147.

REFERENCES

42. Ibrahim, Y. E., Ismail, M. A., & Nabil, M. (2017). Response of reinforced concrete frame structures under blast loading. *Procedia Engineering*, 171, 890–898. <https://doi.org/10.1016/j.proeng.2017.01.384>
43. Improving communications in wartime conditions is vital for the security and stability of the population. (2025). *Voice of Ukraine*. Retrieved from <https://www.golos.com.ua/article/384261>
44. Iuorio, O., Dauda, J. A., & Lourenço, P. B. (2021). Experimental evaluation of out-of-plane strength of masonry walls retrofitted with oriented strand board. *Construction and Building Materials*, 269, 121358. <https://doi.org/10.1016/j.conbuildmat.2020.121358>
45. Jule, L., Zhuye, H., Cedric, M., & Xiaosheng, J. (2020). Structural installation of precast concrete elements. *Journal of Engineering*, 8, 1–8. <https://doi.org/10.15640/jea.v8n2a1>
46. Karavan, V. V. (2022). Results of technical inspection of buildings affected by blast waves from missile attacks. *Resource-Efficient Materials, Structures, Buildings and Constructions*, 42, 213–222. <https://doi.org/10.31713/budres.v0i42.024>
47. Kaskiv, V. I., Panibratets, L. H., Stepanov, S. M., Hriniv, V. S., & Chaikovska, L. I. (2024). State of bridge infrastructure of Ukraine on state roads in government-controlled territories for 2023. *Roads and Bridges*, 29, 280–292. <https://doi.org/10.36100/dorogimosti2024.29.280>
48. Kaskiv, V. I., Zavhorodnii, S. S., & Borysenko, M. A. (2023). Inspection of bridges damaged or destroyed by explosions. *Roads and Bridges*, 27, 168–176. <https://doi.org/10.36100/dorogimosti2023.27.168>
49. Khalil, M., Ruggieri, S., & Uva, G. (2022). Assessment of structural behavior, vulnerability, and risk of industrial silos: State-of-the-art and recent research trends. *Applied Sciences*, 12(6), 3006. <https://doi.org/10.3390/app12063006>
50. Kharkiv Housing Challenge & Northern Saltivka Reconstruction Project. Retrieved from <https://architecturecompetitions.com/kharkivhousingchallenge/>
51. Kim, C. G., Lee, R. M., Park, H. C., & Hwang, U. B. (2002). Impact damage of honeycomb sandwich antenna structures. *Transactions of the Korean Society of Mechanical Engineers A*, 26(2), 387–398. <https://doi.org/10.3795/KSME-A.2002.26.2.387>
52. Kim, C. K., Lee, L. M., Park, H. C., Hwang, W., & Park, W. S. (2003). Impact damage and antenna performance of conformal load-bearing antenna structures. *Smart Materials and Structures*, 12, 672. <https://doi.org/10.1088/0964-1726/12/5/302>
53. Kliuchnyk, S. V., & Hernych, M. V. (2023). Restoration of infrastructure objects as an element of sustainable development on the example of one bridge. *Bridges and Tunnels: Theory, Research, Practice*, 24, 31–36. <https://doi.org/10.15802/btrp2023/291780>
54. Kliuchnyk, S. V., & Horbatiuk, Yu. M. (2025). Experience in restoration of destroyed road engineering structures. *Bridges and Tunnels: Theory, Research, Practice*, 22, 49–54. <https://doi.org/10.15802/btrp2022/268222>
55. Klymenko, S. V., Dorofiev, V. S., Dovzhenko, O. O., Kostiuk, A. I., Posternak, O. O., Chernieva, O. S., Lysenko, Ye. V., Liashenko, T. V., & Melnyk, M. V.

(2012). Building Structures: A Textbook (E. V. Klymenko, Ed.). Kyiv: Center for Educational Literature. ISBN 978-617-673-068-2.

56. Knyziak, P. (2014). Estimating the technical deterioration of large-panel residential buildings using artificial neural networks. *Procedia Engineering*, 91, 394–399. <https://doi.org/10.1016/j.proeng.2014.12.082>

57. *Largest number of destroyed bridges in Chernihiv region.* (2025). Retrieved from <https://cntime.cn.ua/najbilsha-kilkist-zrujnovanih-mostiv-na-chernigivs-article/>

58. Liu, S., Long, C., Xu, C., & Liu, X. (2024). Numerical simulation of autoclaved aerated concrete masonry walls subjected to close-in explosions. *Shock and Vibration*, 2024, Article 8850303.

59. Luccioni, B., Ambrosini, R., & Danesi, R. (2004). Analysis of building collapse under blast loads. *Engineering Structures*, 26, 63–71. <https://doi.org/10.1016/j.engstruct.2003.08.011>

60. Makhin'ko, A., & Makhin'ko, N. (2021). *Steel tanks for grain storage* (Vol. 1). Kyiv: Stal Publishing House.

61. Malazdrewicz, S., Ostrowski, K. A., & Sadowski, Ł. (2022). Large panel system technology in the second half of the twentieth century – Literature review, recycling possibilities and research gaps. *Buildings*, 12, 1822. <https://doi.org/10.3390/buildings12111822>

62. Melashenko, Yu., Slyusarenko, Yu., Ishchenko, Yu., & Pavliuk, Ye. (2023). Experience of inspecting panel houses damaged by hostilities. *Science and Construction*, 36(2). <https://doi.org/10.33644/2313-6679-2-2023-5>

63. Meneliuk, O., Meneliuk, I., & Russkyi, V. (2023). Study of the condition of buildings and structures damaged by warfare. *Construction Production*, 75, 17–26. <https://doi.org/10.36750/2524-2555.75.17-26>

64. Methodology for examining buildings and structures damaged as a result of emergencies, hostilities and terrorist acts. (2022). *Order of the Ministry of Community and Territorial Development of Ukraine*, No. 65 (April 28, 2022).

65. MinRegion of Ukraine. (2022). DBN V.2.6-221:2021. *Steel corrugated-wall silo structures for grain: Fundamental provisions*. Kyiv: Ministry for Communities and Territories Development of Ukraine.

66. Minregionbud of Ukraine. (1998). *Enterprises, buildings and structures for grain storage and processing: DBN V.2.2-8-98* (with Amendment No. 1). Kyiv: State Committee for Urban Development and Architecture.

67. Mishchenko, R., & Hasenko, A. (2025). Analysis of damages to bearing structures of engineering structures for planning resource-saving technologies and their accelerated restoration. *IOP Conference Series: Earth and Environmental Science*, 1499(1), 012070. <https://doi.org/10.1088/1755-1315/1499/1/012070>

68. Mobile communication in the Armed Forces of Ukraine: Myth and reality. (2024). *Territorial Defense Forces*. Retrieved from <https://cutt.ly/dwI5Qpvt>

69. Mollaei, S., Dehcheshmeh, M. M., & Khalighi, S. (2022). Investigation of behavior of masonry walls constructed with autoclaved aerated concrete blocks under blast loading. *Applied Sciences*, 12(17), 8725. <https://doi.org/10.3390/app12178725>

REFERENCES

70. Molodid, O. S. (2025). *Methods for restoring building structures damaged by non-design impacts: A monograph*. Kyiv: Lira-K Publishing.
71. Molodid, O., Kovalchuk, O., Skochko, V., Plokhuta, R., Molodid, O., & Musiiaka, I. (2023). Inspection of war-damaged buildings and structures: The case of Borodianka urban settlement. *Strength of Materials and Theory of Structures*, 110, 328–343. <https://doi.org/10.32347/2410-2547.2023.110.328-343>
72. Nowakowski, P. (2020). Functional and aesthetic aspects of modernization of large-panel residential buildings. https://doi.org/10.1007/978-3-030-20151-7_32
73. Nuzhnyi, V. (2022). Initial studies of building and structure damages caused by warfare. *Building Structures: Theory and Practice*, 11, 104–114. <https://doi.org/10.32347/2522-4182.11.2022.104-114>
74. Oksen, Ye. I., Dombrovskyi, Ya. I., Tytarenko, V. A., & Shuminskyi, V. D. (2024). Features of assessing the technical condition of a pedestrian bridge damaged by warfare. *Sc. and Constr.*, 39(1), 21–28. <https://doi.org/10.33644/2313-6679-1-2024-3>
75. Oksenko, K. O. (2024). *Reliability assessment of spiral-seam silos for bulk materials*. Poltava: National University “Yurii Kondratiuk Poltava Polytechnic”.
76. Ozcelik, Y., Cigeroglu, E., & Caliskan, M. (2025). Shock response of an antenna structure considering geometric nonlinearity. *Nonlinear Dynamics*, 1, 47–59. <https://doi.org/10.1007/978-3-319-29739-2-6>
77. Ozkula, G., Dowell, R. K., Baser, T., et al. (2023). Field reconnaissance and observations from the February 6, 2023, Turkey earthquake sequence. *Natural Hazards*, 119(1), 663–700. <https://doi.org/10.1007/s11069-023-06143-2>
78. Pichugin, S. F., Semko, O. V., Trusov, G. M., Bibik, V. M., & Hasenko, A. V. (2012). Typical damage to load-bearing structures of warehouse and industrial buildings and ways to prevent their formation. *Resource-Saving Materials, Structures, Buildings and Constructions*, 23, 715–720.
79. Pochapskyi, M. D., Butnik, S. V., & Pomazan, M. D. (2022). Prospects of precast-monolithic construction for restoring objects in Ukraine. *Con. Prod.*, 74, 35–41.
80. ProPM Construction. (2024). *Rapid construction technologies*. Retrieved from <https://propm.pro/pmo-for-ukrainian-communities>
81. Radio Svoboda. (2024). *Missile strike on the Military Institute of Communications in Poltava*. Retrieved from <https://www.radiosvoboda.org/a/shcho-vidomo-pro-trahediyu-v-poltavi/33104602.html>
82. Russia launched 12 missiles at Zaporizhzhia: Residential buildings destroyed. Retrieved from <https://suspilne.media/zaporizhzhia/291054-vnaslidok-masovanogo-raketnogo-udaru-po-zaporizzu-zrujnovani-zitlovi-budinki/>
83. Russyi, V. V. (2021). Analysis of examples of war-related damage in brick buildings. *Scientific Bulletin of Construction*, 104(2), 208–211. <https://doi.org/10.29295/2311-7257-2021-104-2-208-211>
84. Rybka, A. (2003). Large-panel dwelling building: Current state – Ways of construction and architectural modifications. *European Cooperation in Science and Technology*, 12, 207–216.

85. Saad, A. M., Gorse, C., Goodier, C. I., Blay, K., & Pialarissi-Cavalaro, S. (2024). Autoclaved aerated concrete in reinforced building applications: A systematic review of AAC/RAAC in the last 40+ years. *Results in Engineering*, 24, 103431. <https://doi.org/10.1016/j.rineng.2024.103431>
86. Semko, O. V., & Hasenko, A. V. (2022, June 29–30). Undesirable redistribution of efforts in damaged building structures and measures to eliminate it. In *Proceedings of the All-Ukrainian Scientific-Practical Forum “WE WILL WIN – WE WILL REBUILD!”* (pp. 91–93). Dnipro: PDABA.
87. Semko, V. O., & Pashynskiy, M. V. (2020). *Architecture of buildings and structures. Architectural structures of low-rise civil buildings* (3rd ed., rev. and enl.). Kropyvnytskyi: Central Ukrainian National Technical University. Retrieved from <https://dspace.kntu.kr.ua/handle/123456789/10159>
88. Suspilne Poltava. (2025, April 2). [Results of the examination of the building on Balenka Street in Poltava, which was hit by a rocket, became known]. *Suspilne News*. <https://suspilne.media/poltava/984697-stali-vidomi-rezultati-ekspertizy-budynku-na-vulici-balenka-u-poltavi-kudi-vlucila-raketa/> [in Ukrainian]
89. Suspilne Poltava. (2025, February 4). [15 lives: Poltava residents who died as a result of the rocket attack on February 1]. *Suspilne News*. <https://suspilne.media/poltava/940285-14-zittiv-poltavci-aki-zaginuli-vnaslidok-raketnogo-obstrilu/> [in Ukrainian]
90. *T4P War Crimes Database Statistics*. Retrieved from <https://t4pua.org/stats>
91. Tabarkevych, O., Serhiichuk, V., & Tabarkevych, N. (2023). Restoration of residential buildings in Chernihiv region damaged by shelling. *Science and Construction*, 37(3). <https://doi.org/10.33644/2313-6679-3-2023-7>
92. Telecom Front: How mobile operators resist blackouts, restore connectivity, rebuild the destroyed, and help the Armed Forces of Ukraine. (2022). *MIND (Special Project: Modern Chronicle of Ukrainian Business)*. Retrieved from <https://surl.li/tykahm>
93. Thango, S. G., Stavroulakis, G. E., & Drosopoulos, G. A. (2023). Investigation of the failure response of masonry walls subjected to blast loading using nonlinear finite element analysis. *Computation*, 11(8), 165. <https://doi.org/10.3390/computation11080165>
94. The Masonry Society (TMS). (2022). TMS 402/602-22: Building code requirements and specification for masonry structures.
95. The Russian Federation carried out about 10 drone strikes in the Kharkiv region in the morning: In some areas there are interruptions in TV and radio signals. (2024). Public Kharkiv. Retrieved from <https://suspilne.media/kharkiv/705516-rf-zavdala-blizko-10-udariv-bezpilotnikami-vranci-po-harkivsini-u-deakih-rajonah-e-pereboi-z-tb-ta-radiosignalom/>
96. Types of precast systems. (2025). Retrieved from <https://db.world-housing.net>
97. U.S. Department of Defense. (2022). UFC 4-010-01: DoD minimum antiterrorism standards for buildings.
98. Wardach, M., Pawłowicz, J. A., Kosior-Kazberuk, M., & Krentowski, J. R. (2023). The diagnostics of the condition and management of large-panel buildings

REFERENCES

using point clouds and building information modelling (BIM). *Buildings*, 13, 2089. <https://doi.org/10.3390/buildings13082089>

99. Yi, W. J., Yi, F., & Zhou, Y. (2021). Experimental studies on progressive collapse behavior of RC frame structures: Advances and future needs. *International Journal of Concrete Structures and Materials*, 15, 31. <https://doi.org/10.1186/s40069-021-00469-6>

100. Zahreba, V. (2025). Bridges in Ukraine: Crisis, problems, solutions (Analytical Report). *Policy Paper*. Retrieved from <https://visionzero.org.ua/images/855220c980bf404b99d06d9191bd5fc4.pdf>

101. Zelenko, Ye., Yakovenko, M., Zorin, Ye., Nesterenko, O., & Ben, I. (2025). Limit deformations of geometric parameters of grain storages (steel silos) and assessment of their technical condition based on geodetic surveys. *Science and Construction*, 42(4). <https://doi.org/10.33644/2313-6679-4-2024-3>

102. Zhang, C., Gholipour, G., & Mousavi, A. A. (2020). Blast loads induced responses of RC structural members: State-of-the-art review. *Composites Part B: Engineering*, 195, 108066. <https://doi.org/10.1016/j.compositesb.2020.108066>

103. Zhang, Y., & Li, B. (2023). Current status and future challenges of autoclaved aerated concrete. *Journal of Structural Engineering*. <https://doi.org/10.1061/PPSCFX.SCENG-1302>